



| 8<sup>TH</sup> JUNE 2020

# Initial Experiences of Premium Rail Steels on London Underground

Andy Vickerstaff, Principal Engineer Track Components &  
Configuration, Transport for London



EVERY JOURNEY MATTERS

# Contents

- Changing rail failure modes
- Initial premium rail installations
- Identified issues
- Performance Indicators
- Developing the Strategy



# Wear Dominated Railway



EVERY JOURNEY MATTERS



# 4 Wear Dominated Railway



EVERY JOURNEY MATTERS

# RCF/Corrugation Dominated Railway







# RCF leading to UUR



## <sup>7</sup> Why is it untestable?




# Whole Life Rail Model










# Wheel-Rail Forces



# Whole Life Rail Model




# 400m v 200m Radius Curves







# S-Stock 260 v 335: High Rail



# S-Stock 260 v 335: Low Rail



# Cant Def v Torque: W2L for 92TS





# <sup>15</sup> Broken Premium Rail





# <sup>16</sup> Broken Premium Rail





# <sup>17</sup> Severe Defects in Premium Rail







18

# 200m Curve in HP335

260




335



19

# 400m Curve in HP335




335

3MGT

12MGT

18MGT

260





13MGT

25MGT

28MGT





# High Rail Wear






# Low Rail Wear




# Rail Deflection: Trackform



# Rail Deflection: Flash Butt Welds




# Crack Angle





# Plastic Deformation



	HP 335	R260
Depth of Deformation	15 – 110 $\mu\text{m}$ (Mean 38 $\mu\text{m}$ )	135 – 293 $\mu\text{m}$ (Mean 206 $\mu\text{m}$ )
Crack Initiation Angle	22 - 47° (Mean 36°)	23 - 65° (Mean 34°)



# Conclusions

- Crack initiation angle appears similar but turns much more quickly in 335
- LUL suffers from centre railhead cracks caused by trailing axles in tightest curves
- Leads to mainly UUR with very shallow crack depths in 260 but lower risk of leading to fast fracture in 335
- Rail deflection certainly appears to be a contributing factor as sites with new track with less issues?
- Depth of work hardening layer much greater in 260 providing a layer of protection?
- Higher wear in gauge corner removing cracks at sufficient rate?
- 80% of the cost of re-railing is in the process so very little performance improvement to justify extra material costs
- Currently trialling a 400 grade heat treated site but very interested in bainitics because....



# Is wear a bad thing?

