



# **Squat-Type Defects in Light Rail: Experiences in Inspections, Laboratory Tests, and Maintenance Approaches**

**Presentation to ICRI - CM**

**20 September 2025**

# Overview

---

- Squat-type Defects
  - Characteristics and causes
- Transit Experience
  - Inspections and Technologies
  - Studies – metallurgical, monitoring, root causes
  - Maintenance Strategies
  - Summary
- Next Steps
  - Defect initiation – wheel slips and martensite

# Squat-Type Defects

---

- Also referred to as studs
- Definitive root cause not identified
  - Theories, contributing factors, and exceptions




# Squats vs Squat-Type Defects (Studs)

Squats	Studs
<ul style="list-style-type: none"><li>• RCF initiated usually at gauge corner</li><li>• Martensite may be present</li><li>• 40-100 MGT to develop</li><li>• Clear unidirectional plastic deformation (ratcheting) of the surface layer</li><li>• Cracks follow sheared inter-granular ferrite</li></ul> <p>Cracks initiate at about 20° to rail surface</p> <ul style="list-style-type: none"><li>• Hydraulic entrapment common</li><li>• Can progress to TD's</li><li>• Found in locations with high driving traction</li><li>• Are most common on the high rail of curves</li></ul>	<ul style="list-style-type: none"><li>• Wheel slip initiated in middle of running band</li><li>• Martensite always present</li><li>• <b>Can develop within 10 MGT</b></li><li>• Minimal subsurface plastic deformation exists</li><li>• Cracks wander around and through pearlite grains</li><li>• No consistent crack angle inclination</li><li>• Hydraulic entrapment not involved</li><li>• <b>Not seen to progress to TDs and broken rails</b></li><li>• Found in locations with high driving and braking traction</li><li>• Can be found in high, low and tangent rails</li></ul>

# Squat-Type Defects - Characteristics


- Several millimetres across the railhead
- Before spalling can cause rough ride
- Damage fasteners, ballast, ride quality, noise & vibration
- Increase track and vehicle maintenance
  - Substantially shortens the usable rail life
- Appear the same as Squats, but causes and consequences are different





# Squat-Type Defects - Characteristics

- Almost no plastic deformation
- Formation within 10 MGT or less
- Old and new rails, tangent and curves
- Presence of WELs
- Not found in tunnels



# Squat-Type Defects – contributing factors


- Premium Heat Treat rails
  - Increased hardness, strength, similar toughness
  - Increased wear and RCF resistance
  - Studs form in areas with low rail wear
- Anti-head check profiles
  - Gauge corner undercutting
  - Concentrating contact on TOR
- White Etching Layers
  - Contributing factor but usually wear away
- Traction Effort
  - DC to AC, multiple driven axles
  - Significant increase of traction forces in last 30 years
- System Stiffness
  - High system stiffness will increase dynamic reaction



# Squat-Type Defects


- Surface defect size can create an exception in APTA or other track standards developed by North American standards resulting in slow orders or watch and proceed
- Some maintenance activities like rail head welding have caused rail breaks that are associated, indirectly, with squat-type defects
- Early rail replacement / reduced asset life

**Why do some areas develop studs while others, with similar operational characteristics, do not?**





# Squat-Type Defects - Consequences







# Inspection and Technologies

- Initial mostly visual observations
  - Lead to creation of a rail damage tracking sheet for area of concern
- A series of slow orders and stop and proceed required an increased effort in understanding and documenting what was going on
- Use of different technologies included:
  - Eddy Current (Rohmann Draisine)
  - EMFI (RAGA)
  - Ultrasonic Testing B-Scans (Sperry)
  - Accelerometers
  - Corrugation Trolley

SOUTH BOUND TRACK		NORTH BOUND TRACK			
WEST RAIL	EAST RAIL	WEST RAIL	EAST RAIL		
				Spalling	
				Shelly Spots/ Squats	Newly Developing
				Gauge Face Flaking	
				Shelling Gauge Face	
				Defects corrected with grinding	
				0	
				11.9	
				11.95	




# Eddy Current



# EMFI

- EMFI tow behind unit was trialed and returned almost zero defects
  - Further calibration is required and the technology still could be promising
- Ongoing scope of work to calibrate technology
  - Better pick up studs and possible rail head weld repairs (to pre-emptively map out possible locations for future failures)





# Ultrasonic Testing

- Review of the B-Scans and comparison between damaged rail and good condition rail
  - Promising results in terms of mapping out “infected” rail versus clean but no obvious signs to show severity (yet)
- Recommendation for client to adjust their customer profile to better target and map out rail conditions
  - An east coast passenger railway system did something similar to provide more granular detail as, again, defects weren’t apparent with prior specifications

Right  
Rail

Head

Web

Base

Left  
Rail

37 and 70 transducers showing up here





0 degree transducer not continuous

37 and 70 transducers showing up here

0 degree transducer not continuous


# Accelerometers

- Axle box accelerometers can give some information on areas with the presence of these defects




# Corrugation Trolley

- Rail roughness measurements taken regularly in tandem with Eddy Current measurements
  - Mapped out and identified squat-type defects almost as reliably, possibly more-so as depressions form in the rail head without exposed cracks
  - If EC can't provide meaningful depth values for studs then perhaps rail roughness measurement can be just as useful to map out and rank for severity







# Root Cause Analysis

- NRC/ARM report results on metallurgy, martensite, hardness, crack characteristics






# Root Cause Analysis



Element	C755-3	C755-4	IJ-3	SB-1	ER-3	AREMA Standard [23]	AREMA Intermediate [23]
Al	<0.005	<0.005	<0.005	<0.005	<0.005		max 0.005
C	0.84	0.82	0.80	0.91	0.91		0.72 - 0.82
Co	0.008	0.008	0.008	0.01	0.009		-
Cr	0.22	0.22	0.2	0.22	0.22	0.25 - 0.40	0.40 - 0.70
Cu	0.24	0.24	0.2	0.21	0.21		max 0.4
Mn	1.01	1.01	0.99	1.07	1.06	0.80 - 1.10	0.70 - 1.25
Mo	0.02	0.02	0.01	0.03	0.03		max 0.05
Nb	<0.005	<0.005	<0.005	<0.005	<0.005		-
Ni	0.09	0.08	0.08	0.09	0.09		max 0.15
P	0.011	0.011	0.014	0.017	0.017		max 0.020
S	0.01	0.011	0.012	0.009	0.009		max 0.020
Si	0.31	0.31	0.32	0.32	0.31	0.10 - 0.50	0.10 - 1.00
Ti	0.016	0.016	0.018	0.016	0.015		-
V	<0.005	<0.005	<0.005	<0.005	<0.005		max 0.01

# Ongoing Monitoring

- Ongoing monitoring for the hunt for incipient studs
- Search for early/shallow martensitic layers or other indicators





# Ongoing Monitoring



30JUL24




23JAN25



10JUL25



# Ongoing Monitoring



30JUL24



23JAN25

10JUL25





# Ongoing Monitoring



30JUL24



23JAN25



10JUL25






# Ongoing Monitoring



30JUL24



23JAN25




10JUL25





# Ongoing Monitoring

30JUL24



23JAN25



10JUL25



# Ongoing Monitoring

- Sight ground a month or two before inspection in July 2025



04NOV24



23JAN25



10JUL25






# Maintenance Strategies

---

- Rail head weld repairs – abandoned
- Rail Grinding
  - Corrective – abandoned, made things “worse”
  - Preventive – acoustic approach, maintain profiles, natural wear
- Rail Milling
  - Corrective – Various success
  - Preventive – minimum removal, but what’s the timing, what’s the cost, and what is the depth required
- Friction Management
  - TORFM be a reasonable approach for next step?


# Rail Grinding





# Rail Milling


- Rail Milling program in one curve provide detailed analysis on metal removal, eddy current, and photos with dye penetrant
- Initial visual assessment and EC measurement did not typically match to expected level of effort



1<sup>st</sup> Pass




2<sup>nd</sup> Pass



3<sup>rd</sup> Pass




# Rail Milling




EC Readings (Channel 2 of 4)


Original



2<sup>nd</sup> Measurement



3<sup>rd</sup> Measurement





# Summary

---

- Studs are an issue, possibly not a direct safety issue, but still a concern on performance and asset life
- We, and others, have not seen rail breaks directly from studs
  - Mixed review/reports from some other agencies
- So far nothing has reliably given us the incipient rail defect
  - Preventive maintenance to just follow 10 MGT? That is a lot of grinding... not a lot of metal removal but a lot of track time and resource allocation
- Milling has restored profiles and preventive grinding has slowed/prevented return and growth of defects
  - At large metal removal though

# Knowledge Gaps

---

- Martensite – a buildup of martensite layers or single events, most vehicles or rogue incidents, maintenance equipment.
  - Thickness/depth is key? WEL and/or BEL?
- Crack growth – tonnage accumulation before detectable crack develops and what technology, if any, can find it early enough
- Role of contact patch size, contact stress?
- Preventive grinding adequate for control?
- Is corrugation a contributor to or result of studs?
- What role do harder steels play?

# Next Steps

---

- Continue to monitor key locations and trend/track
  - What's a good inspection frequency and, visually, what are we looking for
- Non-destructive testing of martensite formation and depth
  - Track, time, and plan maintenance
  - Does technology exist? Magnetic Barkhausen Noise Analysis?
- Friction management (top of rail)
  - Control friction level and minimize stick/slip
  - Decreases the range in friction levels within a segment
- Track and monitor adhesion events
  - Data loggers from trains, map out severity/frequency in segments
- Other ideas?