
# Effects of the lack of rail grinding on the rail maintenance

HENRIQUE CAROU



Henrique Carou
Specialist Engineer
MetroRio
hcosta@metrorio.com.br






#### Case study of a metropolitan system


- Characteristics:
- Low Axle load
  - 17t/axle
- Short Headway
  - 3 minutes minimum
- 6 car configuration
- Standard 115-RE rails
- Slab and Ballasted track
- Elastic fastenings

#### Lubrication improvement An mid-journey




ICRI Workshop, August 27, 2023, Rio de Janeiro


#### Causes of rail fracture



- **RCF**
- Pré aquecimento da solda
- Fuga de corrente
- Fadiga mecânica
- HOT TEAR
- falha de vedação no cordão da solda
- Fragilização por Inclusão de material da solda cadweld no metal base do trilho

ICRI Workshop, August 27, 2023, Rio de Janeiro







RCF

- What is it?
- How it starts?
- How is the evolution?

#### RCF examples






ICRI Workshop, August 27, 2023, Rio de Janeiro

#### Fractures Examples




ICRI Workshop, August 27, 2023, Rio de Janeiro

#### Lifespan of the track considering wear



ICRI Workshop, August 27, 2023, Rio de Janeiro

## Prevision of accumulated rail replacement over the years



ICRI Workshop, August 27, 2023, Rio de Janeiro



### RCF Control / Treatment

- Rail reprofiling
  - Growth prevention
  - Wheel x rail contact maintenance




#### Harder Rails

Reduce defect. creation rate

47% increased lifespan

Gradual hardness avoid fragility

Hard on top and tenacious on bottom



Fonte: Voestalpine

ICRI Workshop, August 27, 2023, Rio de Janeiro

